# Symbol 2D Omnidirectional Presentation USB Scanner

Setup/Reset Sequence

1. Scan **Set Factory Defaults.**

✂ ···

2. Scan **Add an Enter Key.**

✂ ···

Note: You may have to perform the entire sequence more than once to reset the Symbol 2D Omnidirectional Presentation Scanner. If the reset does not resolve scanner performance issues, please contact Exatouch Tech Support at 1-800-966-5520 – Option 3, or go to help.exatouch.com.